

## WYKAZ STALI ZBROJENIOWEJ DLA RYSUNKÓW kw-7.1, kw-7.2, kw-7.3, kw-7.4

parter – zb.górne – 1 szt.								
	38	10	9990	14	1	14		139.9
	39	10	1920	201	1	201		385.9
	40	10	3600	14	1	14		50.4
	41	10	1200	94	1	94		112.8
	42	10	1440	16	1	16		23.0
	43	10	5440	8	1	8		43.5
	44	10	1900	6	1	6		11.4
	45	10	1360	39	1	39		53.0
	46	10	2320	264	1	264		612.5
	47	10	12000	125	1	125		1500.0
	48	10	3125	20	1	20		62.5
	49	10	1960	78	1	78		152.9
	50	10	3600	40	1	40		144.0
	51	10	3270	39	1	39		127.5
	52	10	2955	259	1	259		765.3
	53	10	5545	52	1	52		288.3
	54	10	2390	85	1	85		203.2
	55	10	4595	85	1	85		390.6
	56	10	6015	65	1	65		391.0
	57	10	4435	42	1	42		186.3
	58	10	5020	65	1	65		326.3
	60	10	1960	65	1	65		127.4
	61	10	3590	32	1	32		114.9
	62	10	4460	20	1	20		89.2
	63	10	2500	39	1	39		97.5
	65	10	2070	207	1	207		428.5
	66	10	5864	18	1	18		105.6
	67	10	12000	18	1	18		216.0
	68	10	3640	54	1	54		196.6
	69	10	6756	9	1	9		60.8
	70	10	3580	293	1	293		1048.9
	71	10	4260	27	1	27		115.0
	74	10	2255	13	1	13		29.3